	Туре	L#	Hits	Search Text
1	BRS	L1	14060	hub near3 bearing
2	BRS	L2	2744	hub near3 bearing.clm.
3	BRS	L3	2046	1 and (flange).clm.
4	BRS	L4	783	3 and (wheel).clm.
5	BRS	L5	87	4 and (sens\$5 detect\$5 transducer measur\$5).clm.
6	BRS	L6	42	5 and (force load pressure strain stress).clm.
7	BRS	L7	6	6 and (optical\$5)
8	BRS	L8	2	"6658943"
9	BRS	L10	13	"6158124"
10	BRS	Lll	16	"5952587"
11	BRS	L12	8	"5488871"
12	BRS	L13	21	"5140849"
13	BRS	L14	15	"4642500"
14	BRS	L9	12	"6161962"
15	BRS	L15	5	9 and (flange)
16	BRS	L16	5	15 and (sens\$5 detect\$5 transducer measur\$5)
17	BRS	L18	2	17 and (optical\$5)
18	BRS	L17	5	16 and (force load pressure strain stress)
19	BRS	L19	2	17 and (optical\$5)
20	BRS	L20	278	73/862.191

	DBs	Time Stamp	Comments	Error Definition	Erro rs
1	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
2	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:10			0
3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
4	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:11			0
5	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:28			0
6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:08			0
7	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:29			0
8	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:27			0
9	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:27			0
10	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:27			0
11	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:27			0
12	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:27			0
13	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:27			0
14	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:28			0
15	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:28			0
16	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:29			0
1 <i>7</i>	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:38			0
18	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:39			0
19	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:38			0
20	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 14:39			0

	Туре	L#	Hits	Search Text
21	BRS	L21	2	20 and hub near3 bearing
22	BRS	L22	224383	optical near2 (sens\$5 detect\$5 transducer measur\$5)
23	BRS	L23	31649	optical near2 (sens\$5 detect\$5 transducer measur\$5).clm.
24	BRS	L24	190	23 and (hub).clm.
25	BRS	L25	12	24 and (flange).clm.
26	BRS	L26	8	25 and bearing
27	BRS	L27	5	26 and (force load pressure strain stress).clm.

	DBs	Time Stamp	Comments	Error Definition	Erro rs
21	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:06			0
22	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
23	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
24	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
25	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
26	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:07			0
27	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 15:08			0